Ni Operating Limit<sub>2</sub> = Opacity<sub>2</sub> × E-Cat<sub>st</sub> × 
$$\frac{Q_{mon,st}}{R}$$

(Eq. 10)